

Project Goal
Client
Location
Project
Soakage reports

Various

Various

5462	Quentin Avenue Onehunga Auckland	<ul style="list-style-type: none"> • Our engineering staff recommended that two new soakholes be put in place after catchment runoff calculations.
5542	Charlton Avenue Mt Eden Auckland	<ul style="list-style-type: none"> • Storm water disposed via rockbore soakhole. • Proposed individual pre-treatment devices and rockbore soakholes after water runoff calculations.
6049	Mt Eden Road Mt Eden Auckland	<ul style="list-style-type: none"> • Confirmation of existing soakholes appropriate for the continued collection of runoff from the roof. • Proposal of a new rockbore soakhole to accommodate the excess runoff.
5613	Rawhiti Road Onehunga Auckland	<ul style="list-style-type: none"> • Runoff directed via settling chamber for pretreatment prior to the existing soakhole.

